

Chain of Custody Sheet	Monroe One BOCES Water Testing Summary for 04-18-2017 Retests					EPA Action Level = 15 ug/L<	Paradigm Report Page #	Work order for "DO NOT DRINK" sign	Work order for piping remediation
	Sample ID	Building	Room	Fixture	Address	Result Lead ug/L			
1	420-119595-1	Foreman Center Bldg 1,2,3	P-02	Single Kitchen Sink, 1 faucet	41 O'Connor Rd	4.1	5	NA	NA
1	420-119595-2	Foreman Center Bldg 8	A-05	Right sink, Women's Locker Room	41 O'Connor Rd - Pool Bldg	2.9	6	NA	NA
1	420-119595-3	Foreman Center Bldg 4,5,6	Y-11A*	Left faucet of three faucet sink	38 O'Connor Rd	1.0	7	NA	NA
1	420-119595-4	Foreman Center Bldg 4,5,6	X-10A*	Left faucet of three faucet sink	38 O'Connor Rd	1.0	8	NA	NA
1	420-119595-5	Alternate High Bldg 9,10	C-01	Single Kitchen Sink, 1 faucet	25 O'Connor Rd	1.0	9	NA	NA
1	420-119595-6	Alternate High Bldg 9,10	D-03	Single Kitchen Sink, 1 faucet	25 O'Connor Rd	6.5	10	NA	NA
1	420-119595-7	Alternate High Bldg 9,10	F-01	Single Kitchen Sink, 1 faucet	25 O'Connor Rd	8.3	11	NA	NA

*A is left faucet, B is center faucet on triple faucet sinks and the right faucet on dual faucet sinks, and C is the right faucet on triple faucet sinks.