

<b>Monroe One BOCES</b> <b>Building 9,10: Alternate HS</b> <b>25 O'Connor Rd, Fairport NY 14450</b>					EPA Action Level > 15 ug/L	<b>Lab Sample ID</b> <b>420-168029-xx</b>	Report Page #	<b>Testing Date:</b> <b>February 18, 2020</b>
<b>Building</b>	<b>Floor</b>	<b>Room</b>	<b>Chain of Custody Sample Number</b>	<b>Fixture</b>	<b>Result Lead ug/L</b>			<b>Time Sampled</b>
			1b	Removed				
			2b	Removed				
25 O'Connor Rd	1	A-07	3b	Single Kitchen Sink	1.00	<b>7</b>	12 of 46	9:35 AM
			4b	Removed				
			5b	Removed				
25 O'Connor Rd	1	A-Hall x A-06	6b	Drinking Fountain	1.00	<b>8</b>	13 of 46	9:34 AM
25 O'Connor Rd	1	C-01	7b	Main Office, Sink	7.34	<b>9</b>	14 of 46	9:17 AM
25 O'Connor Rd	1	C-03B	8b	Single Kitchen Sink	3.05	<b>10</b>	15 of 46	9:18 AM
25 O'Connor Rd	1	C-03B1	9b	Kitchen Sink, Left	1.00	<b>11</b>	16 of 46	9:18 AM
25 O'Connor Rd	1	C-03B1	10b	Kitchen Sink, Right	1.00	<b>12</b>	17 of 46	9:18 AM
25 O'Connor Rd	1	D-10D	11b	Single Kitchen Sink	4.41	<b>13</b>	18 of 46	9:27 AM
25 O'Connor Rd	1	D-03	12b	Single Kitchen Sink	30.50	<b>14</b>	19 of 46	9:32 AM
25 O'Connor Rd	1	D-08	13b	Single Kitchen Sink	6.27	<b>15</b>	20 of 46	9:31 AM
25 O'Connor Rd	1	D-10A	14b	3 Bay, Left Faucet	1.71	<b>16</b>	21 of 46	9:27 AM
25 O'Connor Rd	1	D-10B	15b	3 Bay, Right Faucet	1.36	<b>17</b>	22 of 46	9:27 AM
25 O'Connor Rd	1	D-10C	16b	Ice maker	1.00	<b>18</b>	23 of 46	9:28 AM
25 O'Connor Rd	1	E-Hall	17b	Drinking Fountain	1.00	<b>19</b>	24 of 46	9:20 AM
25 O'Connor Rd	1	F-01	18b	Single Kitchen Sink	4.48	<b>20</b>	25 of 46	9:24 AM
25 O'Connor Rd	1	F-05	19b	Single Kitchen Sink	1.00	<b>21</b>	26 of 46	9:22 AM
25 O'Connor Rd	1	F-06	20b	Single Kitchen Sink	1.00	<b>22</b>	27 of 46	9:22 AM
25 O'Connor Rd	1	F-Hall x F-03	21b	Drinking Fountain	1.00	<b>23</b>	28 of 46	9:23 AM
			22b	Removed				
25 O'Connor Rd	2	B-Hall by B-01	23b	Drinking Fountain	1.0	<b>24</b>	29 of 46	9:38 AM

Note 3

Science Lab Sink to remain, it is signed Don-potable water, DO NOT DRINK.