

Monroe One BOCES Bldg 1,2,3 & Bldg 4,5,6: Creekside & EMCC 41 & 25 O'Connor Rd, Fairport NY 14450					EPA Action Level > 15 ug/L	Lab Sample ID 420-168028-xx	Report Page #	Testing Date: February 18, 2020
Building	Bldg Area	Room	Chain of Custody Sample Number	Fixture	Result Lead ug/L			Time Sampled
41 O'Connor Rd	1M	A-02	1	Lab Sink	1.00	1	7 of 109	7:59 AM
41 O'Connor Rd	1M	A-Hall x A-05	2	Drinking Fountain	1.00	2	8 of 109	7:57 AM
41 O'Connor Rd	1M	D-02	3	3 Bay Sink, Faucet Left	7.98	3	9 of 109	7:52 AM
41 O'Connor Rd	1M	D-02	4	3 Bay Sink, Faucet Right	1.00	4	10 of 109	7:52 AM
41 O'Connor Rd	1M	D-02	5	Ice Machine	1.00	5	11 of 109	7:52 AM
41 O'Connor Rd	1M	D-08	6	3 Bay Sink, Faucet Left	1.00	6	12 of 109	7:55 AM
41 O'Connor Rd	1M	D-08	7	3 Bay Sink, Faucet Right	1.00	7	13 of 109	7:55 AM
41 O'Connor Rd	1M	D-08	8	Ice Machine	1.00	8	14 of 109	7:56 AM
41 O'Connor Rd	1M	E-05	9	Single Kitchen Sink, 1 faucet	9.52	9	15 of 109	7:49 AM
41 O'Connor Rd	1M	E-06a	10	Single Kitchen Sink, 1 faucet	6.36	10	16 of 109	7:48 AM
41 O'Connor Rd	2M	G-01	11	3 Bay Sink, Faucet	1.00	11	17 of 109	7:43 AM
41 O'Connor Rd	2M	G-01	12	Hand Sink by 3 Bay	1.00	12	18 of 109	7:44 AM
41 O'Connor Rd	2M	G-01	13	Ice machine	1.00	13	19 of 109	7:46 AM
41 O'Connor Rd	2M	G-01	14	Single Kitchen Sink, 1 faucet	1.00	14	20 of 109	7:44 AM
41 O'Connor Rd	2M	G-Hall x H-02	15	Drinking fountain	1.00	15	21 of 109	7:41 AM
41 O'Connor Rd	2M	H-02	16	Single Kitchen Sink, 1 faucet	5.78	16	22 of 109	7:40 AM
41 O'Connor Rd	2M	H-09	17	Drinking Fountain	1.00	17	23 of 109	7:38 AM
41 O'Connor Rd	2M	J-08	18	3 Bay Sink, Faucet Left	1.00	18	24 of 109	7:34 AM
41 O'Connor Rd	2M	J-08	19	3 Bay Sink, Faucet Right	1.00	19	25 of 109	7:34 AM
			20	# not used when sampling				
41 O'Connor Rd	2M	J-08	21	Cook Station Hand Washing Sink	3.16	20	26 of 109	7:35 AM
41 O'Connor Rd	2M	J Jall x J-11	22	Drinking Fountain	1.00	21	27 of 109	7:31 AM
41 O'Connor Rd	2M	J-08	23	Kitchen Sink near Coffee Station	1.87	22	28 of 109	7:35 AM
41 O'Connor Rd	2M	J-09	24	Kitchen Sink	8.70	23	29 of 109	7:32 AM
41 O'Connor Rd	2M	J-10	25	Kitchen Sink, Left	2.90	24	30 of 109	7:29 AM
41 O'Connor Rd	2M	J-10	26	Kitchen Sink, Right	1.67	25	31 of 109	7:29 AM
41 O'Connor Rd	2M	L-01	27	Single Kitchen Sink, 1 faucet	5.09	26	32 of 109	7:30 AM
41 O'Connor Rd	3U	G-17	28	Single kitchen sink drinking fountain	1.00	27	33 of 109	7:07 AM
41 O'Connor Rd	3U	G-17	29	Single Kitchen Sink faucet	1.00	28	34 of 109	7:07 AM
41 O'Connor Rd	3U	G-18	30	Single Kitchen sink drinking fountain	1.00	29	35 of 109	7:08 AM
41 O'Connor Rd	3U	G-18	31	Single Kitchen Sink faucet	1.00	30	36 of 109	7:08 AM
41 O'Connor Rd	3U	G-19	32	Single Kitchen sink drinking fountain	1.00	31	37 of 109	7:10 AM
41 O'Connor Rd	3U	G-19	33	Single Kitchen Sink faucet	1.35	32	38 of 109	7:10 AM
41 O'Connor Rd	3U	G-20	34	Kitchen Sink, Health Suite East	2.82	33	39 of 109	7:12 AM
41 O'Connor Rd	3U	G-22	35	Single Kitchen sink drinking fountain	1.00	34	40 of 109	7:15 AM
41 O'Connor Rd	3U	G-22	36	Single Kitchen Sink faucet	1.00	35	41 of 109	7:15 AM
41 O'Connor Rd	3U	G-Hall x G-22	37	Drinking Fountain	1.00	36	42 of 109	7:17 AM
41 O'Connor Rd	3U	J-14	38	Drinking Fountain at Sink	1.00	37	43 of 109	7:26 AM
41 O'Connor Rd	3U	J-14	39	Sink Faucet	1.00	38	44 of 109	7:26 AM
41 O'Connor Rd	3U	J-15	40	Drinking Fountain at Sink	1.00	39	45 of 109	7:24 AM
41 O'Connor Rd	3U	J-15	41	Sink Faucet	1.46	40	46 of 109	7:24 AM
41 O'Connor Rd	3U	J-16	42	Drinking Fountain at Sink	1.00	41	47 of 109	7:21 AM
41 O'Connor Rd	3U	J-16	43	Kitchen Sink	1.00	42	48 of 109	7:21 AM
41 O'Connor Rd	3U	J-17A	44	Kitchen Sink, Left	1.00	43	49 of 109	7:23 AM
41 O'Connor Rd	3U	J-17B	45	Kitchen Sink, Right	1.00	44	50 of 109	7:23 AM

Monroe One BOCES Bldg 1,2,3 & Bldg 4,5,6: Creekside & EMCC 41 & 25 O'Connor Rd, Fairport NY 14450						EPA Action Level > 15 ug/L	Lab Sample ID 420-168028-xx	Report Page #	Testing Date: February 18, 2020
Building	Bldg Area	Room	Chain of Custody Sample Number	Fixture	Result Lead ug/L			Time Sampled	
41 O'Connor Rd	3U	M-01	46	Drinking Fountain at Sink	1.31	45	51 of 109	7:18 AM	
41 O'Connor Rd	3U	M-01	47	Kitchen Sink	2.57	46	52 of 109	7:18 AM	
41 O'Connor Rd	3U	M-02	48	Kitchen Sink, Health Suite North	1.27	47	53 of 109	7:13 AM	
41 O'Connor Rd	3U	M-02	49	Kitchen Sink, Health Suite South	1.55	48	54 of 109	7:13 AM	
			50	# not used when sampling					
41 O'Connor Rd	3U	M-04	51	Drinking Fountain at Sink	1.74	49	55 of 109	8:25 AM	
41 O'Connor Rd	3U	M-04	52	Kitchen Sink	1.48	50	56 of 109	8:25 AM	
41 O'Connor Rd	3U	M-05	53	Drinking Fountain	1.82	51	57 of 109	8:23 AM	
41 O'Connor Rd	3U	M-05	54	Kitchen Sink	2.00	52	58 of 109	8:23 AM	
41 O'Connor Rd	3U	M-08	55	Drinking Fountain at Sink	1.00	53	59 of 109	8:22 AM	
41 O'Connor Rd	3U	M-08	56	Kitchen Sink	1.00	54	60 of 109	8:22 AM	
41 O'Connor Rd	3U	M-11	57	Drinking Fountain at Sink	1.00	55	61 of 109	8:21 AM	
41 O'Connor Rd	3U	M-11	58	Kitchen Sink	1.00	56	62 of 109	8:21 AM	
41 O'Connor Rd	3U	M-12	59	Drinking Fountain at Sink	38.60	57	63 of 109	8:19 AM	
41 O'Connor Rd	3U	M-12	60	Kitchen Sink	2.27	58	64 of 109	8:19 AM	
			61	# not used when sampling					
41 O'Connor Rd	3U	M-13	62	Kitchen Sink	1.00	59	65 of 109	NIS	
41 O'Connor Rd	3U	M-Hall x M-04	63	Drinking Fountain, Left	5.62	60	66 of 109	8:18 AM	
41 O'Connor Rd	3U	M-Hall x M-04	64	Drinking Fountain, Right	1.70	61	67 of 109	8:26 AM	
41 O'Connor Rd	3U	P-01	65	Drinking Fountain at Sink	7.47	62	68 of 109	8:26 AM	
41 O'Connor Rd	3U	P-01	66	Kitchen Sink	15.70	63	69 of 109	8:06 AM	
41 O'Connor Rd	3U	P-02	67	Drinking Fountain at Sink	34.30	64	70 of 109	8:06 AM	
41 O'Connor Rd	3U	P-02	68	Kitchen Sink	8.49	65	71 of 109	8:07 AM	
41 O'Connor Rd	3U	P-03	69	Drinking Fountain at Sink	2.24	66	72 of 109	8:07 AM	
41 O'Connor Rd	3U	P-03	70	Kitchen Sink	1.26	67	73 of 109	8:08 AM	
41 O'Connor Rd	3U	P-04G	71	Single Kitchen sink drinking fountain	1.00	68	74 of 109	8:08 AM	
41 O'Connor Rd	3U	P-04G	72	Single Kitchen Sink faucet	1.00	69	75 of 109	8:11 AM	
41 O'Connor Rd	3U	P-05	73	Kitchen Sink	1.00	70	76 of 109	8:11 AM	
41 O'Connor Rd	3U	P-10	74	Kitchen Sink, 1 faucet, Left	1.21	71	77 of 109	8:12 AM	
41 O'Connor Rd	3U	P-10	75	Kitchen Sink, Right	1.00	72	78 of 109	8:14 AM	
41 O'Connor Rd	3U	P-14	76	Single Kitchen Sink, 1 faucet	1.00	73	79 of 109	8:14 AM	
			77	# not used when sampling					
41 O'Connor Rd	3L	Q-04	78	Single Kitchen Sink, 1 faucet	2.77	74	80 of 109	8:16 AM	
41 O'Connor Rd	3L	Q-10	79	Kitchen Sink 1 faucet, near door	1.00	75	81 of 109	8:36 AM	
41 O'Connor Rd	3L	Q-10	80	Sink near window	1.82	76	82 of 109	8:35 AM	
41 O'Connor Rd	3L	Q-Hall x TRQA	81	Drinking Fountain	1.00	77	83 of 109	8:36 AM	
41 O'Connor Rd	3L	R-01	82	Sink	2.06	78	84 of 109	8:36 AM	
41 O'Connor Rd	3L	R-01	83	Drinking Fountain	1.85	79	85 of 109	8:37 AM	
41 O'Connor Rd	3L	R-06E	84	Sink	9.06	80	86 of 109	8:47 AM	
			85	# not used when sampling					
			86	# not used when sampling					
			87	# not used when sampling					
41 O'Connor Rd	3L	U-09D	88	Single Kitchen Sink, 1 faucet	1.00	81	93 of 109	8:41 AM	
41 O'Connor Rd	3L	V-Hall x V-08	89	Drinking Fountain	1.00	82	94 of 109	8:38 AM	
41 O'Connor Rd	2M	J-08	90	Ice Machine	1.00	83	89 of 109	8:39 AM	

38 O'Connor Rd	Main	W by W-13	1a	Drinking Fountain	1.00	1	6 of 46	9:03 AM
38 O'Connor Rd	Main	W by W-5B	2a	Drinking Fountain	1.00	2	7 of 46	9:04 AM
			3a					
38 O'Connor Rd	Main	X-10	4a	Drinking Fountain	1.00	3	8 of 46	9:07 AM
38 O'Connor Rd	Main	X-Hall by X-6	5a	Drinking Fountain	1.00	4	9 of 46	9:02 AM
38 O'Connor Rd	Main	Y-08	6a	Drinking Fountain	1.00	5	10 of 46	9:08 AM
38 O'Connor Rd	Main	Y-1 Hall x Y-02	7a	Drinking Fountain	1.00	6	11 of 46	9:10 AM

Note1 Outlet to be removed from service.