

Monroe #1 BOCES Water Testing December 29, 11:00 AM										NYS Action Level = 5 ppb	Paradigm Report Page #	Work order for "DO NOT DRINK" sign	Work order for piping remediation
Chain of Custody Sheet	Sample ID 226113-xx	Building	Room	Fixture	Address	Count	Result Lead ppb						
1	1	1	Bldg 1,2,3	B-02	Nail Tech	South Wall Sink	41 O'Connor Rd	1	< 1	2			
2	1	2	Bldg 1,2,3	B-04	Sm Cos	West Wall Sink	41 O'Connor Rd	1	< 1	3			
3	1	3	Bldg 1,2,3	B-04	Sm Cos	South Wall Sink	41 O'Connor Rd	1	1.1	4			
4	1	4	Bldg 1,2,3	B-05A	Spa	Sink East Wall	41 O'Connor Rd	1	1.8	5			
5	NOT TESTED		Bldg 1,2,3	B-05	Spa	Sink South Wall	41 O'Connor Rd		NOT TESTED - NO FAUCET				
6	1	5	Bldg 1,2,3	B-01	Lg Cos B-01	South Wall Sink	41 O'Connor Rd	1	1.6	6			
7	1	6	Bldg 1,2,3	A-05	Lg Cos A-05	West North (R) Wall Sink	41 O'Connor Rd	1	< 1	7			
8	1	7	Bldg 1,2,3	A-07	Three Seasons	Hand Sink	41 O'Connor Rd	1	< 1	8			
9	1	8	Bldg 1,2,3	D-07	Training Kitchen1	Hand Sink	41 O'Connor Rd	1	< 1	9			
10	1	9	Bldg 1,2,3	D-07	Training Kitchen1	3 Bay Sink L Faucet 1	41 O'Connor Rd	1	< 1	10			
11	2	10	Bldg 1,2,3	D-07	Training Kitchen1	3 Bay Sink R Faucet 2	41 O'Connor Rd	1	< 1	11			
12	2	11	Bldg 1,2,3	D-07	Training Kitchen1	Island Hand Sink	41 O'Connor Rd	1	< 1	12			
13a	2	12	Bldg 1,2,3	D-07	Training Kitchen1	Pot Filler 1 North East	41 O'Connor Rd	1	< 1	13			
13b	2	13	Bldg 1,2,3	D-07	Training Kitchen1	Pot Filler 2 North Middle	41 O'Connor Rd	1	1.1	14			
13c	2	14	Bldg 1,2,3	D-07	Training Kitchen1	Pot Filler 3 North West	41 O'Connor Rd	1	< 1	15			
13d	2	15	Bldg 1,2,3	D-07	Training Kitchen1	Pot Filler 4 South East	41 O'Connor Rd	1	1.6	16			
13e	2	16	Bldg 1,2,3	D-07	Training Kitchen1	Pot Filler 5 South West	41 O'Connor Rd	1	< 1	17			
14	2	17	Bldg 1,2,3	D-08	Taining Kitchen 2	Pot Filler 1 North East	41 O'Connor Rd	1	< 1	18			
15	2	18	Bldg 1,2,3	D-08	Taining Kitchen 2	Pot Filler 2 North Middle	41 O'Connor Rd	1	< 1	19			
16	3	19	Bldg 1,2,3	D-08	Taining Kitchen 2	Island Hand Sink	41 O'Connor Rd	1	< 1	20			
17	3	20	Bldg 1,2,3	D-08	Taining Kitchen 2	Island 3 Bay - 1 Faucet	41 O'Connor Rd	1	< 1	21			
18	3	21	Bldg 1,2,3	D-08	Taining Kitchen 2	3 Bay Sink Left Faucet 1	41 O'Connor Rd	1	< 1	22			
19	3	22	Bldg 1,2,3	D-08	Taining Kitchen 2	3 Bay Sink Right Faucet 2	41 O'Connor Rd	1	< 1	23			
20	NOT TESTED		Bldg 1,2,3	D-08	Taining Kitchen 2	Pot Filler 3 North West	41 O'Connor Rd	1	NOT TESTED - NO WATER				
21	3	23	Bldg 1,2,3	D-08	Taining Kitchen 2	Pot Filler 4 South East	41 O'Connor Rd		1	24			
22	3	24	Bldg 1,2,3	D-08	Taining Kitchen 2	Pot Filler 5 North West	41 O'Connor Rd	1	2.1	25			
23	NOT TESTED		Bldg 1,2,3	D-08	Taining Kitchen 2	Hand Sink East (door wall)	41 O'Connor Rd		NOT TESTED				
		Bldg 1,2,3	TR-B02	Nail Tech TR	Toilet Sink	Posted "DO NOT DRINK" signs					78951		
		Bldg 1,2,3	TR-B04	Sm Cos TR	Toilet Sink						78952		
		Bldg 1,2,3	TR-A05	Lg Cos A-05 TR	Toilet Sink						78953		
		Bldg 1,2,3	TR-B01	Lg Cos B-01 TR	Toilet Sink						78954		
		Bldg 1,2,3	TR-DA	Wm's Student TR	5 TR Sinks						78955		
		Bldg 1,2,3	TR-DB	Mn's Student TR	5 TR Sinks						78956		
		Bldg 1,2,3	D-1A	Janitor's Closet	Mop Sink						78961		
		Bldg 1,2,3	TR-CA	Staff GN TR	Toilet Sink						78962		
		Bldg 1,2,3	TR-CB	Staff GN TR	Toilet Sink						78963		
		Bldg 1,2,3	TR-CC	Staff GN TR	Toilet Sink						78964		
		Bldg 1,2,3	TR-CD	Staff GN TR	Toilet Sink	78965							

ts given in mg/L, 1 mg/L = 1,000 ppb